## List of Machinery in Safwan, Basrah owned by Metalex

			GROUP 1
ITEM NO	Qty.	Description	UNIT INFO
Mac	hinery		
1	1	100,000 lb. Excavator CAT345BL-II	S/N:CAT0345BAFEE00279
3	1	CAT 583 K Pipelayer 594 Sidebooms -no winch	S/N 78V00869 Newly Serviced S/N:PIP0002
4	1	Dozer CAT D8R w/winch	Dozer CAT D8R w/ Winch year 2005 (Delivery end June 2005) S/N:001449
5 6	1	RTB CASE 580SR Fuel Storage, Skid mounted	S/N:N4GH01602 3000 Gal. Capacity
7 8	6 1	Manual Barrel Pumps Hydraulic Pulling Unit	S/N:006606, (250,000 lb. Pull Capacity) - Draw works w/ controls Ex: Timberland, Skaigit
9	1	Utility Truck Flat Bed Truck	Two Ton Capacity, (w/stake side panels) (Topkick)
10	1	F250 Crew cab PU (4WD/ diesel) equipped with 100 Gal. fuel tank	S/N:4XB05221
11	1	Mechanic Truck F550 Fully Equipped (w/tools for cat	S/N:B77548
12	1	equipment / small to large tools) 40' Sea Container (Pigs) - no Shelves	S/N:956927
13	2	40' Sea Container (Misc. Tools) w/ shelving	S/N:937121&937122
14	3	1-Pole / 4 Light (Light Towers)	Ingersoll Rand Light Tower IR L6-4MH Powered by Kobota Diesel Engine, Serial Nos.: 349048UHO822; 349039UHO822; 349042UHO822
15	1	4-Wheel ATV (Diesel if Possible)	
16 17	1	Ingersoll Rand 250 cfm Air Compressor 30T Cherry Picker RTC8030	Model 4045DF270, Serial Nos.: SCZ751FXX5Y520948; SCZ771FXX5Y521026 S/N:145612
18	9	200 to 250 amp welding mach. Diesel (possible mounted	500amp-500X MODEL, S/N:207984,86,87,89,193749,207993,95,97,99
	1	on sleds or trailers) Sandblaster Clemco Model #2452 with accessories	
19 20	1	Capacity 200 ltrs. Hoses (for above item)	S/N:027727
21	1	Nozzles (for above item)	
22	1	Concrete Vibrator Accessories (for above item)	2" Concrete Vibrator - Dynapac Model# AU55 with Accessories, Serial No. 9099849
_	e Hand	ling Tools	
24	12	Nylon Slings Sized to fit 20" pipe	(30,000 lbs. Min. Strength)
25	4	Nylon Slings Sized to fit 30" pipe	(40,000 lbs. Min. Strength)
26 27	2 5	Lower-In Belts w/irons / Size to fit 48" pipe Nylon Slings Sized to fit 48" pipe	(60,000 lbs. Min. Strength)
28	2	40" KC Type Line Up Clamps	with eccentric dog
29 30	2	32" KC Type Line Up Clamps 30" KC Type Line Up Clamps	with eccentric dog with eccentric dog
31	2	26" KC Type Line Up Clamps	with eccentric dog
32 33	2	24" KC Type Line Up Clamps 20" KC Type Line Up Clamps	with eccentric dog with eccentric dog
34	1	18" KC Type Line Up Clamps	man cocomina dag
35 36	2	16" KC Type Line Up Clamps 14" KC Type Line Up Clamps	
37	2	12" KC Type Line Up Clamps	
38 39	2 8	8" KC Type Line Up Clamps 12" Long beveling torches with angle heads	
40	2	40" Beveling Band	
41 42	2	32" Beveling Band 30" Beveling Band	
43	2	26" Beveling Band	
44 45	2	24" Beveling Band 20" Beveling Band	
46	1	16" Beveling Band	
47 48	2 4	Crawlers for beveling bands 18" Beveling Machines	
49	2	12" to 20" Beveling Machines	(12" to 20")
50 51	2	6" to 12" Beveling Machines 6" to 8" Beveling Machines	(6" to 12") (6" to 8")
52	2	4" to 2" Beveling Machines	
53 54	15 35	Bottles Acetylene (300 cu/ft. Min.) Bottles of Oxygen (244 cu/ft. Min)	(225cu/tt. Min.) (220cu/tt. Min.)
55	2	36" Pipe Wrench	
56 57	5 5	24" Pipe Wrenches 18" Pipe Wrenches	
58 59	2	Hammer Wrenches 1" through 4-1/8" Combination wrenches 1" though 4-1/8"	Metric, in sets Metric, in sets
60	4	10 Pound Sledge Hammers	mono, m oce
61 62	8 10	6 Pound Sledge Hammers 4 Pound Sledge Hammers	
63	10	16 oz. ball pein hammers	
64 65	10 10	32" Plastic Night Caps 30" Plastic Night Caps	
66	10	26" Plastic Night Caps	
67 68	10 10	24" Plastic Night Caps 20" Plastic Night Caps	
69	10	16" Plastic Night Caps	
70 71	10 10	14" Plastic Night Caps 12" Plastic Night Caps	
72	10	8" Plastic Night Caps	
73 74	15 15	Cans of White Spray Paint Cans of Blue Spray Paint	Upside down survey type Upside down survey type
75	15	Cans of Red Spray Paint	Upside down survey type
76 77	20	Cans of Orange Spray Paint Cans of Floresent Green Spray Paint	Upside down survey type Upside down survey type
78	100	Rolls Survey Flag Material (Various Colors)	
79 80	25 15	30 lb. Propane bottles (Full) Propane Torches	
		esting Equipment	
81	1	AtlasCopco A/C 847CFMW/150 Feet 3"-4" discharge	S/N:YA3-062656-50506393&YA3-062655-50506417
U I	<u></u>	MODEL XAMS856CD	

82	1	HP Pump 3000 psi (Pressure Washer) MODEL HKY-202 BXRA	S/N: X1825-982
83	50	Feet 1/2" 3000 psi high pressure hose	
84	8	(Lot) Assorted Fittings for High Pressure Testing 6 inch #600 Series RF/WN Flanges Sch/80	
85	12	Sets of Flange Bolts For 6" Flanges	
86 87	40	6" Garlok Flg. Gaskets 6" High Pressure Valves (Flange by Flange)	
88	8	4 inch #600 Series RF/WN Flanges Sch/80	
89	12	Sets of Flange Bolts For 4" Flanges	
90 91	40	4" Garlok Flg. Gaskets 4" High Pressure Valves (Flange by Flange)	
92	25	#6000 2" Threaded Couplings	
93	25	#3000 2" Threaded Couplings	
94 95	20 12	2" Sch 80 Threaded Nipples 6" long 2" Sch 80 Threaded Nipples 4" long	
96	12	2" Sch 80 Threaded Nipples 12" long	
97	25	2" Threaded Ball Valves (3000 psi)	
98 99	4 20	2" Threaded Check Valves (3000 psi) 1/2" Sch 80 Threaded Nipples 6" Long	
100	20	1/2" Sch 80 Threaded Nipples 4" Long	
101	10	1/2" Sch 80 Threaded Nipples 2" Long	
102 103	10 25	1/2" Sch 80 Threaded Close Nippile #6000 1/2" Threaded Couplings	
104	25	#3000 1/2" Threaded Couplings	
105	30	#3000 2" Threaded Couplings	
106 107	15 20	#6000 2" Threaded Couplings 2" Screwed Bull Plugs	
108	30	1/2" Screwed Bull Plugs	
109 110	30 15	1/2" Threaded Ball Valves #3000 1/2" X 1/4" threaded Adapters (Bushings) #6000	
110	15 2	1/2" X 1/4" threaded Adapters (Bushings) #6000 High Quality Ambient Thermometers	
112	1	6x6" Trash Water Pump Self Prime (Skid Mounted) 150 lb	S/N:5069307
113	1	Head Pressure 6 x6" TRASH PUMP HI HEAD W/50 FT HOSES	S/N:AFT02071C
		FT. 6" Aluminum or thin steel pipe with victraulic end	
114	500	couplings Or see next line	Each of the above items require fittings to attach them to welded steel pipe.
115	500	Ft. of 6" high pressure hose complete with appropriate adapters	Each of the above items require fittings to attach them to welded steel pipe.
116	2	6" face diameter high pressure gauge (2000 PSI)	
117	4	4" face diameter low pressure gauge (200 PSI)	
118	3	3" Water Pumps with 20' suction 100' Discharge (Hoses to have Cam-Loc Fittings)	
119	4	100' Sections of 3" discharge hose with Cam-Loc Fittings	
120 121	6	3" Female Cam-Loc hose fittings (Extra) 3" Male Cam-Loc hose fittings (Extra)	
122	1	Set / Dead Weight Tester (Hydrostatic Testing) 100 - 5000	S/N:DWT0017
	1	psi Chandler, Imperial	0/N.DW10011
123 124	1	Temperature Recorder and two boxes of charts Pressure Recorder and two boxes of charts	
125	4	Plumbers Plugs 40"	
126 127	4	Plumbers Plugs 32" Plumbers Plugs 30"	
128	4	Plumbers Plugs 36"	
129	4	Plumbers Plugs 24"	
130 131	6 2	Plumbers Plugs 20" 2 lines Plumbers Plugs 18"	
132		Plumbers Plugs 16"	
133	4	Plumbers Plugs 12"	
134 135	6 5	Plumbers Plugs 8" Weld Caps 40" / Min688 wt.	
136	5	Weld Caps 32" / Min625 wt.	
137	5	Weld Caps 30" / Min625 wt.	
138 139	5 5	Weld Caps 26" / Min625 wt. Weld Caps 24" / Min625wt.	
140	7	Weld Caps 20" / Min500 wt.	
141	2	Weld Caps 18" / Min .500 wt.	
142 143	5 5	Weld Caps 16" / Min .500 wt. Weld Caps 14" / Min .500 wt.	
144	6	Weld Caps 12" / Min500 wt.	
145	6	Weld Caps 8" / Min500 wt.	
<u>Pigs</u>	<u>S</u>		
146	1	40" - 4 cup with sizing plate / Spare Cups	
147 148	1	32" - 4 cup with sizing plate / Spare Cups 30" - 4 cup with sizing plate / Spare Cups	
149	1	26" - 4 cup with sizing plate / Spare Cups	
150	1	24" - 4 cup with sizing plate / Spare Cups	
151 152	1	20" - 4 cup with sizing plate / Spare Cups 2 Lines 16" - 3 cup with sizing plate / Spare Cups	
153	1	16" - 3 cup with sizing plate / Spare Cups	
154	1	12" - 3 cup with sizing plate / Spare Cups	
155 156	1 4	8" - 2 cup with sizing plate / Spare Cups 40" Foam Drying Pigs	
157	4	32" Foam Drying Pigs	
158 159	4	30" Foam Drying Pigs 26" Foam Drying Pigs	
160	4	24" Foam Drying Pigs	
161	4	20" Foam Drying Pigs 2 lines	
162 163	<u>2</u> 4	18" Foam Drying Pigs 16" Foam Drying Pigs	
164	60	14" Foam Drying Pigs	
165	4	12" Foam Drying Pigs	
166 167	4 1	8" Foam Drying Pigs 40" Red CrisCross Poly Pigs	
168	1	32" Red CrisCross Poly Pigs	
169	1	30" Red CrisCross Poly Pigs	
170 171	1	26" Red CrisCross Poly Pigs 24" Red CrisCross Poly Pigs	
172	1	20" Red CrisCross Poly Pigs 2 Lines	
173	1	18" Red CrisCross Poly Pigs	

174	6	16" Red CrisCross Poly Pigs	
175	6	14" Red CrisCross Poly Pigs	
176	6	12" Red CrisCross Poly Pigs	
177	6	8" Red CrisCross Poly Pigs	
178	2	40" cleaning / brush pigs / Spare Cups and Brushes	
179	2	32" cleaning / brush pigs / Spare Cups and Brushes	
180	2	30" cleaning / brush pigs / Spare Cups and Brushes	
181	2	26" cleaning / brush pigs / Spare Cups and Brushes	
182	2	24" cleaning / brush pigs / Spare Cups and Brushes	
183	2	20" cleaning / brush pigs / Spare Cups and Brushes 2	
		Lines	
184	2	16" cleaning / brush pigs / Spare Cups and Brushes	
185	2	12" cleaning / brush pigs / Spare Cups and Brushes	
186	2	8" cleaning / brush pigs / Spare Cups and Brushes	
187	1	2" Hot Tap Machine / Related equipment, fittings etc.	TD Williamson
107		Valves & TOL's (Rigid)	To Williamson
188	40	Chill Bands / Rings A-336 Material For 40" Pipe (Rolled at	
100	40	19.35" Radius)	
189	40	Chill Bands / Rings A-336 Material For 30" Pipe (Rolled at	
100	40	14.50" Radius)	
190	40	Chill Bands / Rings A-336 Material For 32" Pipe (Rolled at	
130	40	15.50" Radius)	
191	40	Chill Bands / Rings A-336 Material For 26" Pipe (Rolled at	
191	40	12.50" Radius)	
192	40	Chill Bands / Rings A-336 Material For 24" Pipe (Rolled at	
192	40	11.50" Radius)	
102	60	Chill Bands / Rings A-336 Material For 20" Pipe (Rolled at	
193	60	9.5" Radius)	
194	15	Chill Bands / Rings A-336 Material For 18" Pipe (Rolled at	
194	15	8.5" Radius)	
195	40	Chill Bands / Rings A-336 Material For 16" Pipe (Rolled at	
190	40	7.5" Radius)	
196	20	Chill Bands / Rings A-336 Material For 14" Pipe (Rolled at	
150	20	6.5" Radius)	
197	20	Chill Bands / Rings A-336 Material For 12" Pipe (Rolled at	
197	20	5.5" Radius)	
198	20	Chill Bands / Rings A-336 Material For 8" Pipe (Rolled at	
150	20	3.99" Radius)	
Pro	tol Coa	ting Equipment	
199	1	Protol 7200 Coating Material	
200	6	Hand Drill, 3/8" Drive	
201	200	Hand Rollers / Regular Paint Rollers	(Home Depot Type)
202	6	Spy Holiday Detectors (Jeeps)	Model #725 3 springs for each size pipe.40, 32, 30, 26, 24, 20, 18, 16, 14, 12, 8
203	25	Empty Buckets	
204	75	Pounds FBE Patch Sticks (Fusion bonded epoxy)	
205	12	Plumber propane torches for patch sticks.	
Cor	icrete (	Coating Equipment	
000	2	Carpenter Tools / Hand Tools, Saws, Hammers, Nails,	(Everything as a Set)
206			
		Level	
Wel	ding S	upplies	
<u>Wel</u>	ding S	wpplies Welding Hoods (Black Fiber Metal or Hobart)	
207 208	40 30	Upplies Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets	
207 208 209	40 30 3000	Upplies  Welding Hoods (Black Fiber Metal or Hobart)  Welding Jackets  Welding Clear lens	
207 208 209 210	40 30 3000 50	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear Iens #9 Dark Lens	
207 208 209 210 211	40 30 3000 50 50	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens	
207 208 209 210 211 212	40 30 3000 50 50 3000	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers	
207 208 209 210 211 212 213	40 30 3000 50 50 30 20	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners	
207 208 209 210 211 212 213 214	40 30 3000 50 50 30 20	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered	
207 208 209 210 211 212 213 214 215	40 30 3000 50 50 30 20 10 6	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone	
207 208 209 210 211 212 213 214 215 216	40 30 3000 50 50 30 20 10 6	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc	
207 208 209 210 211 212 213 214 215 216 217	40 30 3000 50 50 30 20 10 6 1500 1500	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes	
207 208 209 210 211 212 213 214 215 216 217 218	40 30 3000 50 50 50 20 10 6 1500 1500	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes	
207 208 209 210 211 212 213 214 215 216 217 218 219	40   30   3000   50   50   30   20   10   6   1500   150   90	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes)	
207 208 209 210 211 212 213 214 215 216 217 218 219 220	ding Si 40 30 3000 50 50 50 30 20 10 6 1500 1500 1500 90 200	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves	
207 208 209 210 211 212 213 214 215 216 217 218 219 220 221	ding S  40 30 3000 50 50 50 30 20 10 6 1500 1500 1500 90 200 50	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP	
207 208 209 210 211 212 213 214 215 216 217 218 219 220 221	ding Si 40 30 300 50 50 50 10 6 1500 1500 1500 1500 150	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners	c/w torch gauges and 100' Hose
207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222	40 30 3000 50 50 50 10 6 1500 1500 1500 200 50 150 90 200 50 150	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs	c/w torch, gauges and 100' Hose.
207 208 209 210 211 211 212 213 214 215 216 217 218 219 220 221 222 223 224	ding Si 40 30 300 50 50 50 10 6 1500 1500 1500 1500 150	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips	c/w torch, gauges and 100' Hose.
207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225	ding S  40  30  30  50  50  50  10  6  1500  1500  1500  50  12  6  6  6  10	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips	c/w torch, gauges and 100' Hose.
207 208 209 210 211 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226	40   30   300   50   50   50   150   150   150   150   16   6   6   6   6   6   6   6   10   10	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #1 Standard Cutting Tips	c/w torch, gauges and 100' Hose.
207 208 209 210 211 212 213 214 215 216 217 218 220 221 222 223 224 225 226 227	ding Si  40  30  3000  50  50  50  10  6  1500  1500  1500  200  1500  1500  150  10  4	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips	c/w torch, gauges and 100' Hose.
207 208 209 210 211 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228	ding Si  40  30  300  50  50  50  10  6  1500  1500  1500  150  90  200  10  6  6  10  10  4  4	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips	c/w torch, gauges and 100' Hose.
207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229	ding Si 40 30 300 50 50 50 30 10 6 1500 1500 1500 1500 110 6 6 10 10 4 4	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band	c/w torch, gauges and 100' Hose.
207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230	ding Si  40 30 3000 50 50 50 10 6 1500 1500 1500 50 1500 150	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling band	c/w torch, gauges and 100' Hose.
207 208 209 210 211 211 213 214 215 216 217 218 220 221 222 223 224 225 226 227 228 229 230 231	ding Si  40  30  3000  50  50  50  10  1500  1500  1500  1500  1500  10  40  40  40  40  40  40  40  40	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #5 Standard Cutting Tips #6 Standard Cutting Tips #7 Standard Cutting Tips #8 Standard Cutting Tips #8 Standard Cutting Tips #8 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #8 Button Type Cutting Tips for Beveling Band	
207 208 209 210 211 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 226 227 228 229 230 231 232	ding Si  40  30  30  3000  50  50  50  10  6  1500  1500  150  90  200  50  12  6  6  10  10  4  4  8  25  10  30	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Bowalt Angle Grinders	c/w torch, gauges and 100' Hose.
207 208 209 210 211 211 212 213 214 215 216 217 218 219 220 221 222 223 223 224 225 226 227 228 229 230 231 231 232 233	ding Si  40  30  30  50  50  50  10  6  1500  1500  1500  150  90  200  10  4  4  8  25  10  30  50  50	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses	
207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 224 225 227 228 229 230 231 232 231 232 233	ding Si  40  30  3000  50  50  50  10  6  1500  1500  1500  1500  200  50  12  6  6  10  4  4  4  4  8  8  5  10  30  50  50	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band #3 Button Type Cutting Tips for beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair Of Clear Safety Glasses	
207 208 209 210 211 211 212 213 214 215 216 217 218 219 220 221 222 223 223 224 225 226 227 228 229 230 231 231 232 233	ding Si  40  30  30  50  50  50  10  6  1500  1500  1500  150  90  200  10  4  4  8  25  10  30  50  50	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses	(Dewalt)
207 208 209 210 211 211 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 231 232 234 235	ding Si  40  30  300  50  50  50  10  6  6  1500  1500  1500  150  90  200  12  6  6  10  10  10  10  4  4  8  25  10  30  50  800	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band #3 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" 5P Plus Pounds of 5/32" 5P Plus	(Dewalt)
207 208 209 210 211 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236	ding Si  40  30  30  50  50  50  10  6  1500  1500  1500  50  12  6  6  10  10  4  4  8  25  10  30  50  50  80  800  5950	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" 5P Plus Pounds of 5/32" 5P Plus	(Dewalt) 3.2mm (6010)
Wel 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 231 232 234 235 236 237	ding Si  40 30 3000 50 50 50 10 6 1500 1500 1500 1500 15	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" SP Plus Pounds of 1/3" 5P Plus Pounds of 1/3" 6" 70 Plus	(Dewalt) 3.2mm (6010)
Wel   207   208   209   210   211   212   213   214   215   216   217   218   219   220   221   222   223   224   225   226   227   228   230   231   232   233   234   235   236   237   238   239   239   239   239   239   239   239   239   230   231   232   233   234   235   236   237   238   239   239   240   240   208   208   239   240   240   208   208   239   240   240   208   208   208   239   240   208	ding Si  40 30 3000 50 50 50 50 10 6 1500 1500 1500 1500	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band #3 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" 5P Plus Pounds of 5/32" 5P Plus Pounds Of 3/16" 70 Plus Pound Of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 5/32"	(Dewalt) 3.2mm (6010)
207 208 209 210 211 212 213 214 215 216 217 218 220 221 222 223 224 225 224 225 228 229 230 231 232 231 232 234 235 236 237 238 239 239 240 241	ding Si  40 30 3000 50 50 50 50 10 6 1500 1500 1500 1500	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" SP Plus Pounds of 1/8" SP Plus Pounds of 3/32" 5P Plus Pound Of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 5/32" Pound Of 7018 Low Hydrogen 1/8" Transit/Level	(Dewalt) 3.2mm (6010)
Wel   207   208   209   210   211   212   213   214   215   216   217   218   219   220   221   222   223   224   225   226   227   228   230   231   232   233   234   235   236   237   238   239   239   239   239   239   239   239   239   230   231   232   233   234   235   236   237   238   239   239   240   240   208   208   239   240   240   208   208   239   240   240   208   208   208   239   240   208	ding Si  40 30 3000 50 50 50 10 6 1500 1500 1500 1500 15	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band #3 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" 5P Plus Pounds of 5/32" 5P Plus Pounds Of 3/16" 70 Plus Pound Of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 5/32"	(Dewalt) 3.2mm (6010)
207 208 209 210 211 212 213 214 215 216 217 218 220 221 222 223 224 225 224 225 228 229 230 231 232 231 232 234 235 236 237 238 239 239 240 241	ding Si  40 30 3000 50 50 50 50 10 6 1500 1500 1500 1500	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" SP Plus Pounds of 1/8" SP Plus Pounds of 3/32" 5P Plus Pound Of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 5/32" Pound Of 7018 Low Hydrogen 1/8" Transit/Level	(Dewalt) 3.2mm (6010)
207 208 209 210 211 211 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 233 233 233 233 233 233 233	40   30   30   30   30   30   30   30	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens #110 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #3 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" SP Plus Pounds of 1/8" SP Plus Pound of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 1/8" Transit/Level Tripod for Above 30 foot level rods (English)	(Dewalt) 3.2mm (6010)
207 208 209 210 211 211 213 214 215 216 217 218 220 221 222 223 224 225 226 227 228 229 223 224 225 226 227 228 229 230 231 232 231 232 233 234 235 236 236 237 238 239 240 241 242 243	ding Si  40 30 3000 50 50 50 50 10 6 1500 1500 1500 1500	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band #3 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" 5P Plus Pounds of 3/16" 70 Plus Pound Of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 1/8" Transit/Level Tripod for Above 30 foot level rods (English) Bundles of Survey Lathes	(Dewalt) 3.2mm (6010)
207 208 209 210 211 211 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 233 233 233 233 233 233 233	40   30   30   30   30   30   30   30	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pounds of 5/32" 5P Plus Pounds of 5/32" 5P Plus Pound of 7018 Low Hydrogen 3/16" Pound of 7018 Low Hydrogen 1/8" Transit/Level Tripod for Above 30 foot level rods (English) Bundles of Survey Lathes 6' Probe Bars Standard 3/8" bar / 20 Extra tips / 10 ea. 3'	(Dewalt) 3.2mm (6010)
207 208 209 210 211 211 213 214 215 216 217 218 220 221 222 223 224 225 226 227 228 229 230 231 232 231 232 233 234 235 236 237 238 239 240 241 242 243	ding Si  40 30 3000 50 50 50 50 10 6 1500 1500 1500 1500	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" 5P Plus Pounds of 1/8" 5P Plus Pounds of 3/32" 5P Plus Pound Of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 5/32" Transit/Level Tripod for Above 30 foot level rods (English) Bundles of Survey Lathes Butten Sye De Extra tips / 10 ea. 3' extensions	(Dewalt) 3.2mm (6010)
207 208 209 210 211 211 212 213 214 215 216 217 218 220 221 222 223 224 225 224 225 227 228 229 230 231 231 232 234 235 236 237 238 239 240 241 242 243 244 245	ding Si  40 30 3000 50 50 50 50 10 6 1500 1500 1500 1500	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens #110 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" SP Plus Pounds of 3/16" 70 Plus Pound Of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 1/8" Transit/Level Trippod for Above 30 foot level rods (English) Bundles of Survey Lathes 6' Probe Bars \$1/2" Bar / extra tips 6' Probe Bars \$1/2" Bar / extra tips	(Dewalt) 3.2mm (6010)
207 208 209 210 211 211 213 214 215 216 217 218 220 221 222 223 224 225 226 227 228 229 230 231 232 231 232 233 234 235 236 237 238 239 240 241 242 243	ding Si  40 30 3000 50 50 50 50 10 6 1500 1500 1500 1500	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #3 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band #3 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pair of Clear Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" 5P Plus Pounds of 3/16" 70 Plus Pound Of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 1/8" Transit/Level Tripod for Above 30 foot level rods (English) Bundles of Survey Lathes 6' Probe Bars Standard 3/8" bar / 20 Extra tips / 10 ea. 3' extensions 6' Probe Bars 1/2" Bar / extra tips Line Finder (Metro Tech#850) Converter and Spare	(Dewalt) 3.2mm (6010)
207 208 209 210 211 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 241 242 243	40   30   30   30   30   30   30   30	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #1 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" SP Plus Pounds of 1/8" SP Plus Pounds of 1/8" SP Plus Pounds of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 5/32" Pound Of 7018 Low Hydrogen 1/8" Transit/Level Trippod for Above 30 foot level rods (English) Bundles of Survey Lathes 6' Probe Bars Standard 3/8" bar / 20 Extra tips / 10 ea. 3' extensions 6' Probe Bars Standard 3/8" bar / 20 Extra tips / 10 ea. 3' extensions 6' Probe Bars Standard 3/8" bar / 20 Extra tips / 10 ea. 3' extensions 6' Probe Bars Standard 3/8" bar / 20 Extra tips / 10 ea. 3' extensions	(Dewalt) 3.2mm (6010)
207 208 209 210 211 211 212 213 214 215 216 217 218 220 221 222 223 224 225 224 225 227 228 229 230 231 231 232 234 235 236 237 238 239 240 241 242 243 244 245	ding Si  40 30 3000 50 50 50 50 10 6 1500 1500 1500 1500	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens #110 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #3 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pair of Clear Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" SP Plus Pounds of 3/3" SP Plus Pounds Of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 1/8" Transit/Level Tripod for Above 30 foot level rods (English) Bundles of Survey Lathes 6' Probe Bars 1/2" Bar / extra tips Line Finder (Metro Tech#850) Converter and Spare Batteries Line Finder (Schonsted 92XP GA-72CD (1800 233 7265)	(Dewalt) 3.2mm (6010)
207 208 209 210 211 211 211 213 214 215 216 217 218 220 221 222 223 224 225 226 227 228 229 230 231 232 231 232 234 235 236 237 238 239 240 241 242 243 244 245 246 247	ding Si  40 30 3000 50 50 50 50 10 6 1500 1500 1500 1500	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #1 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" SP Plus Pounds of 1/8" SP Plus Pounds of 1/8" SP Plus Pounds of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 5/32" Pound Of 7018 Low Hydrogen 1/8" Transit/Level Trippod for Above 30 foot level rods (English) Bundles of Survey Lathes 6' Probe Bars Standard 3/8" bar / 20 Extra tips / 10 ea. 3' extensions 6' Probe Bars Standard 3/8" bar / 20 Extra tips / 10 ea. 3' extensions 6' Probe Bars Standard 3/8" bar / 20 Extra tips / 10 ea. 3' extensions 6' Probe Bars Standard 3/8" bar / 20 Extra tips / 10 ea. 3' extensions	(Dewalt)  3.2mm (6010) (7018)
207 208 209 210 211 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 241 242 243	40   30   30   30   30   30   30   30	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #3 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pounds of 1/8" 5P Plus Pounds of 5/32" 5P Plus Pounds of 5/32" 5P Plus Pound Of 7018 Low Hydrogen 3/16" Pound Of 7018 Low Hydrogen 1/8" Transit/Level Tripod for Above 30 foot level rods (English) Bundles of Survey Lathes 6' Probe Bars Standard 3/8" bar / 20 Extra tips / 10 ea. 3' extensions 6' Probe Bars 1/2" Bar / extra tips Line Finder (Metro Tech#850) Converter and Spare Batteries Line Finder (Schonsted 92XP GA-72CD (1800 233 7265) and Spare Batteries Truck /Tractors tamdum axel, Head Units for Flatbeds and	(Dewalt) 3.2mm (6010)
207 208 209 210 211 211 211 213 214 215 216 217 218 220 221 222 223 224 225 226 227 228 229 230 231 232 231 232 234 235 236 237 238 239 240 241 242 243 244 245 246 247	ding Si  40 30 3000 50 50 50 50 10 6 1500 1500 1500 1500	Welding Hoods (Black Fiber Metal or Hobart) Welding Jackets Welding Clear lens #9 Dark Lens #10 Dark Lens Torch Strikers Tip Cleaners Spacing Tools - Tapered Boxes of Soapstone 1/8" x 9" Grinding Disc Bead Brushes 4" Cup Brushes Pair Welding Gloves (Various Sizes) Pair Black Dot Work Gloves 3" Dia. Grinding Rocks 5/8" arbor STOP Pair Tip Cleaners Complete Sets of Hand Cutting Torchs #0 Standard Cutting Tips #1 Standard Cutting Tips #2 Standard Cutting Tips #3 Standard Cutting Tips #4 Standard Cutting Tips #1 Button Type Cutting Tips for Beveling Band #2 Button Type Cutting Tips for Beveling Band #3 Button Type Cutting Tips for beveling Band Dewalt Angle Grinders Pair Dark Safety Glasses Pair of Clear Safety Glasses Pair of Clear Safety Glasses Pair of Clear Safety Glasses Pounds of 1/8" 5P Plus Pounds of 3/16" 70 Plus Pound of 7018 Low Hydrogen 3/16" Pound of 7018 Low Hydrogen 1/8" Transit/Level Tripod for Above 30 foot level rods (English) Bundles of Survey Lathes 6' Probe Bars Standard 3/8" bar / 20 Extra tips / 10 ea. 3' extensions 6' Probe Bars 1/2" Bar / extra tips Line Finder (Metro Tech#850) Converter and Spare Batteries Line Finder (Schonsted 92XP GA-72CD (1800 233 7265) and Spare Batteries	(Dewalt)  3.2mm (6010) (7018)

251	1	Hydraulic (Air) Driven Cold Cutter / w/ machine capabilities	S/N·KN8050005851
252	2	120 bbl. Vacuum Trailer	10K GAL KA0395 S/N:0400VT & KA0395 S/N:400VT2
253		Cases Duct Tape (60 Rolls)	1011 O/LE 1010000 O/11.04007 C 1010000 O/11.4007 IZ
Safe	ety Gea	r and Equipment	
254 255	100 2	Hard Hats (Good Brand) LEL Meters with H2S Capibility	
256		Head Band Type Face Shields	
257	160	Face Shield Replacement Lens Face Shields for head band above	
258	30	Pair NoMex Cover Alls (Various Sizes)	
259 260		First Aid Kits Gallons of Bio Solve (Oil Breakdown Solution)	
261		Hand Sprayers (2 Gal.) (for above item)	
262 263		Life Jackets Fire Extinguishers	
264	100	Charge Cylinders	
265 266		5 Gal Cans ansul powder (Fire Extinguishers) - Refill Earplugs, Pair	
267	1000	Dust Masks	
268		Eye Wash (Sets)	
_	cellane 15		
269 270	15	20' 3/8" Chains Chain Binders	
271 272		7 Ton Come-A-Longs Hoe Mat Hooks with 1.5" Shakles	
273	3	10 Ton Hydraulic Jacks	
274 275	3 400	10000W Watt Generators - Honda Pipeline Skids (4" x 6" x 4' Long hardwood)	10000 Watt Perkin GenSet, Serial Nos.: 175342/48; 140952/92; 162007/99
278	25	Round Point Shovels	
279		Flat Shovels	
280 281	12 25	5 gal. Steel Gas Cans 10 Gal. Drinking Water Cans	
282	25	5 Gal. Drinking Water Cans	
283 284		Paper Cone Drinking Cups (Few Boxes Only) 6' Pry Bars	
285	6	Port-o-Cans / Chemicals (Porta John)	
286 287	2	Bottle Rack for Oxygen & Acetylene 12 Volt Fuel Pumps for Barge	
288	10	3/4" Shakles	
289 290		1" Shakles 1.5" Shakles	
291	10	3/4" Wire Rope Slings1 10' Long	
292 293		1" Wire Rope Slings1 18' Long 5/8" Wire Rope Slings 10' Long	
294	30	3/4" cable Clamps	
295 296		7/8" cable Clamps 1" cable Clamps	
297	15	1.125" cable Clamps	
298 299		Roll 3/4" Wire Cable Roll 1" Wire Cable	
300	1	Roll 1.125" Wire Cable (Min.700 Feet)	
301	3	Cad Weld Kits (Complete) 300 shots Fuel Additave / Diesel / 10 cases of 12 cans auto trans	
302		fluid	
303 304		6' to 8' Ladders (Metal) 20' Alumnium Extension Ladders	
305	20	2"x12"x 16' Long Boards	
306 307		Pounds of #16 Box Nails Pounds of #8 Box Nails	
308	100	2" x 4" X 8' Boards	
309	100	3' x 3' Nomex Blankets to cover coating while welding (Cut at Jobsite)	
310	20	10" - "C" Clamps (Heavy Duty)	
311	5	7/8" x 25' Long Wire Rope Slings / With eyes plated in ends	
312	1	Nitrogen Purge tool / Consist of gauge, 50' 3/8" hose with	
313		couplings to fit gauge Bottles of Nitrogen 244 size	
314	2	Sets Magnetic Jumpers / Consists of 30' #4 welding cable	Magnetic Jumpers / Consists of 30' #6 welding cable with magnets on each end
315		with magnets on each end. Feet of "#0" welding cable	(35mm2)
316	2000	Feet of "#2" welding cable	(50mm2)
317 318		Connector Lugs for weld cable T-300 Pipeline holders / Welding	
319	1	Sheet of Flat Steel Plate 2" X 4' X 8'	
320 321		Sheets of Flat Steel Plate 1.5" X 4' X 8' Sheets of Flat Steel Plate 1" X 4' X 8'	
322	3	Sheets of Flat Steel Plate 3/4" X 4' X 8'	
323 324	3	Sheets of Flat Steel Plate 1/2" X 4' X 8' Sheets of Flat Steel Plate 1/4" X 4' X 8'	
325	10	Pieces of 2" X 1/4" X 20' Long Angle Iron	
326	5	Pieces of 4" X 1/2" X 20' Long Angle Iron Piece of 10" wide X 2" Thick X 20' Long Flat Plate / Barge	
327	1	Anchor	
328 329	10 2	Pieces 2" x 1/4" Flat bar Steel / 20' Long 55 Gal Drums Hydraulic Oil	
330	3	55 Gal Drums S3 Diesel Motor Oil	
331 332		Cases of Chassis Grease (Marfak) Hand Type Grease Guns (Good Ones)	
333	75	Rolls 1/2" Teflon Tape	
334 335		Rolls 3/4" Teflon Tape Bull Horn Type Air Movers (Aluminum and 3' to 4' Long)	
336		50' sections of 3/4" air hose with crow's foot connections.	
337		40' X 40' Tarps	
338	10	20' X 20' Tarps	
339 340		16' X 16' Tarps 12'x12' Welding Shelters/Tents or Material to build	
340		Welding Umblleras	

342	1	930 Series Air Dryer Mfg. S/N:450001	7 Ft. X 7 Ft. Package / Weight 4,200 Lbs.
344	3	Scott Pac Breathing Tanks (Excape Tanks)	S/N:901336,915216,913612
345	1	Gallons of Petrolite Bioside / Kenny Green	
346		Concrete Coating Materials for pipe From Allen Edwards	
340		Co. (Tulsa OK)	
347	1200	Sacks of #3 Blast Sand	
348	30	Plastic 5 gal. buckets / ie. Home Depot type	
349	2500	Ft 1.25" wide banding material with tool and buckles -	
545	2500	Metal	
350	1	LEICA GPS SYSTEM W/GEODETIC RTK RECEIVER,	S/N:LE132893NO
330		ETC.COMPLETE KIT	0/N.EE 132030NO
351	1	Medium Grade Combination Transit/Level (Not Just a	
		Level)	
352	2	30 Ft. Fiber Glass Level Rod / English (engineering scale)	
353	1	TITAN flange alignment tool, (see photo from Website)	(Pipe sizes from 4" up to 40")
354	3	Welder Wrap Arounds 4" to 6" wide and min. 11' Long,	,
354	3	Straight Edge made from Gasket material	
355	3	Welder Wrap Arounds 4" to 6" wide and min. 7' Long,	
333	3	Straight Edge made from Gasket material	
356	15	25' Measuring Tapes	
357	10	100' Measuring Tapes	
358	150	Assorted Nuts & Bolts From 1/4" up to 1-1/2" / Various	
	130	Lengths-IN LBS	
359	4	Welder Pipe Jack Stands	
360	3	4' Long - Medium Grade Carpenter Levels	
361	8	2' Long - Medium Grade Carpenter Levels	
362	8	Torpedo Levels	
363	50	Shoe Handle Type Hand Wire Brushes	
364	1	3/4 Yard Concrete Bucket, Manual Bottom Dump	
365	4	Metal Job Boxes (20 cu/ft), Steel	
366	16	Metal Job Boxes (12 cu/ft), Steel	
367	1	7-1/4" Circular Saw, w/ Spare Blades	
368	20	Trenton Wax Tape No. 2, 4" Pipe Coating	
369	2000	3/8" Nylon Rope, 2000ft.	

			GROUP 2
ITEM NO	Qty.	Description	UNIT INFO
Mac	hinery		
370	1	100,000 lb. Excavator (Extended Reach) 70' Stick (Kebelco 400 Class)	R290LC-7LR 110892
371	1	100,000 lb. Excavator CAT345BL-II	S/N:E00280
372	1	Flexifloats	
374	1	583 Sidebooms w/winch	
375	1	594 Sidebooms (no winch)	583 Sidebooms (no winch)
376	1	Dozer (D-7 Class or larger) w/winch (pit blade or angle)	Dozer CAT D8 w/ Winch year 2005 (Delivery end June 2005)
377	1	RTB Case 580SR S/N:H01628 3000 Gal. Fuel Storage, Skid mounted	Rubber Tire Backhoe/Loader CAT 424
378 379	3	Manual Barrel Pumps	2000 Gal. Fuel Storage
380	1	Two Ton Utility Truck Flat Bed (w/stake side panels) (Topkick)	
381	1	F250 Crew cab PU (4WD/ diesel) equipped with fuel tank	S/N:4XB05223
382	2	40' Sea Container w/ shelving & lights	
383	1	40' Sea Container (Pigs Tools) No shelving	
384	2	1-Pole / 4 Light (Light Tower)	Ingresoll Rand Light Tower, IR 6L-4MH Powered by Kobota Diesel Engine, Serial Nos.: 349045UHO822; 349085UIO22
385	1	4-Wheel ATV (Diesel if Possible)	S/N:550988
386	1	Flexifloats 50' x 60' with 20' wing section on each side (200,000 lb. Capacity)	
387	1200	Feet 1" wire cable for float anchoring	
388	30	1" Cable Clamps	
389	10	4' x 24' Crane Matts	
390	10	8' x 16' Truck Mats	
391	4	200 to 250 amp welding mach. Diesel (mounted on sleds or trailers)	500amp ,500X MODEL, 207985,207994,208000,208001
392	1	Sandblaster with Accessories Model 2452 Serial No. 27704 / Capacity 200 ltrs. Serial No. 27727	Sandblaster with Accessories Model 2452 Serial No. 27704 / Capacity 200 ltrs. Serial No. 27727
393	1	Hoses (for above item)	
394	1	Nozzles (for above item)	
	Hand	ling Tools	
395	8	Nylon Slings Sized to fit 20" pipe	(30,000 lbs. Min. Strength)
396	4	Nylon Slings Sized to fit 30" pipe	(40,000 lbs. Min. Strength)
397	2	Lower-In Belts w/irons / Size to fit 48" pipe	
398	5	Nylon Slings Sized to fit 48" pipe	(60,000 lbs. Min. Strength)
399	1	40" KC Type Line Up Clamps	
400 401	1	32" KC Type Line Up Clamps 30" KC Type Line Up Clamps	
401	1	26" KC Type Line Up Clamps 26" KC Type Line Up Clamps	
402	1	24" KC Type Line Up Clamps	
404	1	20" KC Type Line Up Clamps	
405	1	18" KC Type Line Up Clamps	
406	1	16" KC Type Line Up Clamps	
407	1	14" KC Type Line Up Clamps	
408	1	12" KC Type Line Up Clamps	
409	1	8" KC Type Line Up Clamps	
410	2	Acey. Oxy. Cutting Rigs with Gauges and 100' of Hose and Hand torch	
411	5	12" Long beveling torches with angle heads	
412	2	40" Beveling Band	
413	2	32" Beveling Band	
414	2	30" Beveling Band	
415	2	26" Beveling Band	
416	2	24" Beveling Band	
417 418	2	20" Beveling Band	
418 419	1	18" Beveling Band	
419	l l	16" Beveling Band	

420	4	Crawlers for beveling bands	
421	2	20" Beveling Machines	S/N:009151&9152
422	2	12" to 10" Beveling Machines	(6 to 12 USA)
423	2	8" to 4" Beveling Machines	(3 to 8 USA)
424	2	4" to 2" Beveling Machines Bottles Acetylene (300 cu/ft. Min.)	(1.5 to 4 USA)
425 426	15 35	Bottles of Oxygen (244 cu/ft. Min.)	
426	1	Transit / Level ( will do both )	
428	1	Tripod for above	
429	10	Survey Lathes and hub stakes ( 20 per bundle)	
430	100	Flagging Tape ( Various colors ) 100Total	
431	2	Level Rods 30'( English )	
		6' probe Bars Standard 3/8" bar/20 ea. Extra tips / 10 ea 3'	
432	12	extensions	
433	5	6' probe Bars 1/2" bar / extra tips	
434	1	Line finder (Metro tech #850) Converter and Spare Battery	
404	'	, , , , , , , , , , , , , , , , , , , ,	
435	1	Line Finder (Schonsted 92XP GA-72CD (1800 233 7265 )	
		and Spare Battery	
436	15	White Spray paint ( Upside down Survey type)	
437 438	15 15	Blue Spray paint ( Upside down Survey type)	
438	20	Red Spray paint ( Upside down Survey type) Orange Spray paint ( Upside down Survey type)	
440	20	Floresent Green Spray paint	(Upside down Survey type)
442	1	Medium Grade Combination Transit / Level	(Openido down ourvey type)
443	1	30' Fiberglass Level rod/ English (Engineering Scale)	
444	13	Sets Cables 100' Lead (#2 or larger) 60' ground	
445	1	High Pressure Pump (Challenger)	TPD033 S/N:642005
446	2	600lb 14" Wellneck Flanges	
447	2	Blind Flanges	
448	1	Four Legged Slings W/Hook (25 ft)	
449	5	Diesel Welding Machines 200-250 Amps - BOBCAT	
		250D'S	
450	6	Drop Lights w/ Spare Bulbs	
451	40	Female Coupling (same as Item#121)	
452	40	Male Coupling (same as Item#122)	
453	2	Set of Parts & Service Manuals for Item# 1 & 370	ONLOGO 47
973	1	Truck Tractor TGA33410	S/N:398047
973 977	1	Truck Tractor TGA33410 500AMP WELDER	500X MODEL, S/N:207979
973 977 978	1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER	500X MODEL, S/N:207979 500X MODEL, S/N:207980
973 977 978 979	1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996
973 977 978 979 755	1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978
973 977 978 979	1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996
973 977 978 979 755	1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978
973 977 978 979 755 760	1 1 1 1 1 3	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707
973 977 978 979 755 760 721 722 723	1 1 1 1 1 3 2 2 2	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679
973 977 978 979 755 760 721 722 723 724	1 1 1 1 1 1 3 2 2 2 2	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708819658 S/N:M19664,M19658 S/N:M19681,M19679 S/N:M19449,M19716
973 977 978 979 755 760 721 722 723 724 725	1 1 1 1 1 1 3 2 2 2 2 2	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26° beveling machines 8 TO 12° BEVELING MACHINES 4 TO 8° BEVELING MACHINES 2 TO 4° BEVELING MACHINES 4 TO 8° BEVELING MACHINES	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726	1 1 1 1 1 3 2 2 2 2 2 2	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708819658 S/N:M19664,M19658 S/N:M19681,M19679 S/N:M19449,M19716
973 977 978 979 755 760 721 722 723 724 725 726 730	1 1 1 1 1 3 2 2 2 2 2 2 2	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735	1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 2 2	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761	1 1 1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781	1 1 1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781	1 1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 2 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 1 2 1 1 1 2 1 1 1 1 2 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800	1 1 1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781	1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 2 2 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455	1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 2 1 1 1 1 2 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 5 TO 4" BEVELING MACHINES 6 TO 8" BEVELING MACHINES 6 TO 8" BEVELING MACHINES 7 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527	1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 2 1 1 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527 570 581	1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527 570 581 582 711	1 1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 2 1 1 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C CLUB CAR DIESEL 4X4	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527 570 581 582 711 719	1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 2 1 2	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C CLUB CAR DIESEL 4X4 Holiday Detectors	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527 570 581 582 711 719 720	1 1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40" Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C CLUB CAR DIESEL 4X4 Holiday Detectors Beveling Machines	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527 570 581 582 711 719 720 729	1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C CLUB CAR DIESEL 4X4 Holiday Detectors Beveling Machines Digital Dewpoint	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527 570 581 582 711 719 720 720 720 721 723 724 725 726 730 731 741 741 742 744 745 746 747 747 748 749 749 749 749 749 749 749 749	1 1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 2 1 1 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C CLUB CAR DIESEL 4X4 Holiday Detectors Beveling Machines Digital Dewpoint CAT 345 W/Hammer	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 781 781 781 781 781 781 799 800 455 527 570 581 582 711 719 720 729 729 729 729 729 729 729 729	1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 2 1 1 1 2 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C CLUB CAR DIESEL 4X4 Holiday Detectors Beveling Machines Digital Dewpoint CAT 345 W/Hammer Transfer Pump	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527 570 581 582 711 719 720 729 798 998 999	1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40" Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C CLUB CAR DIESEL 4X4 Holiday Detectors Beveling Machines Digital Dewpoint CAT 345 W/Hammer Transfer Pump Hyd. Torque Wrench	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527 570 581 582 711 719 720 729 798 969 969 947 955	1 1 1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C CLUB CAR DIESEL 4X4 Holiday Detectors Beveling Machines Digital Dewpoint CAT 345 W/Hammer Transfer Pump Hyd. Torque Wrench 12KW Generator	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527 570 581 582 711 719 720 729 798 969 947 947 965 961	1 1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 2 1 1 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C CLUB CAR DIESEL 4X4 Holiday Detectors Beveling Machines Digital Dewpoint CAT 345 W/Hammer Transfer Pump Hyd. Torque Wrench 12KW Generator Yard Spotter Truck	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527 570 581 582 711 719 720 729 729 729 788 799 800 800 800 800 800 800 800 8	1 1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 2 2 1 1 1 2 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C CLUB CAR DIESEL 4X4 Holiday Detectors Beveling Machines Digital Dewpoint CAT 345 W/Hammer Transfer Pump Hyd. Torque Wrench 12KW Generator Yard Spotter Truck Hyd Single Hoist	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527 570 581 582 711 719 720 729 798 969 947 947 965 961	1 1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 2 1 1 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C CLUB CAR DIESEL 4X4 Holiday Detectors Beveling Machines Digital Dewpoint CAT 345 W/Hammer Transfer Pump Hyd. Torque Wrench 12KW Generator Yard Spotter Truck	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677
973 977 978 979 755 760 721 722 723 724 725 726 730 735 761 781 799 800 455 527 570 581 582 711 719 720 729 798 969 947 955 961 1031 1032	1 1 1 1 1 1 1 1 1 3 2 2 2 2 2 2 2 2 2 1 1 2 1 1 1 1	Truck Tractor TGA33410 500AMP WELDER 500AMP WELDER 500AMP WELDER 500AMP WELDER CLUB CAR DIESEL 4X4 600D WLDG MACHINE, 400 AMP WELDER, & 500DX WELDER 22 to 26" beveling machines 8 TO 12" BEVELING MACHINES 4 TO 8" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 2 TO 4" BEVELING MACHINES 4 TO 8" BEVELING MACHINES CLUB CAR DIESEL 4X4 6" pump Challenger Test Pump 40' Container CLUB CAR DIESEL 4X4 Farm Tractor Mobile Work shop/container Air compressor Welding Machine Hyd Cable Winch 185 A/C CLUB CAR DIESEL 4X4 Holiday Detectors Beveling Machines Digital Dewpoint CAT 345 W/Hammer Transfer Pump Hyd. Torque Wrench 12KW Generator Yard Spotter Truck Hyd Single Hoist Hyd Single Hoist Hyd Single Hoist Hyd Single Hoist	500X MODEL, S/N:207979 500X MODEL, S/N:207980 500X MODEL, S/N:207996 XRT1500 4WD, S/N:550978 S/N:LC196971,KJ138345,KG263707 S/N:M19708&19658 S/N:M19664,M19658 S/N:M19581,M19679 S/N:M19449,M19716 S/N:M19478,M19678,M19677